


Attachment B – Photographs







Note: It appears base has collapsed and void under pavement goes to foundation wall (6-12") and then slopes to bottom of hole.