

WDID# 9 37C383506

Chula Vista Site 3 – 12/10/18 Photo Log



1. View of Site 3 along western perimeter where discharge occurred.



2. View of Site 3 erosion rills and sediment plumes along western perimeter.

WDID# 9 37C383506
Chula Vista Site 3 – 12/10/18 Photo Log



3. View of gravel bags deployed.



4. View of gravel bags deployed within erosion rill.

WDID# 9 37C383506
Chula Vista Site 3 – 12/10/18 Photo Log



5. Upstream view of erosion rill and gravel bags within the erosion rill.



6. View of fiber roll at the top of slope along western perimeter.

WDID# 9 37C383506
Chula Vista Site 3 – 12/10/18 Photo Log



7. View of gravel bags and fiber roll at the top of slope along the western perimeter of Site 3.



8. View of gravel bags and fiber roll at erosion rill along western perimeter of Site 3.